



Government of Maharashtra, India

Public Works Department

OFFICE OF THE EXECUTIVE ENGINEER,
PUBLIC WORKS DIVISION, AURANGABAD-431001 PH-0240-2331174

DM/Bldg Fitness/ 680

Date:- 26/9/2020

To,
Principal,
Swami Vivekanand Public School
Aurangabad.



Subject: -Issue Building Fitness & Safety Certificate For School Building
Ref: Sub-1. Your office Ltr No.2020/1/16----Dt.16/01/2020
2.Sub-Divisional Engineer, PW(South)subDivision, Aurangabad
Report Ltr No. Ts/-69-- Dt.24/01/2020.

With reference to above report this is to inform you that Swami Vivekanand Bahuuddeshiya Sevabhavi Vikas Sanstha's SWAMI VIVEKANANAD PUBLIC SCHOOL BUILDING at Gut No. 24/ Part At. village SharnapurTq&DistAurangabad has been completed as per plan sanctioned by Gram PanchayatSharnapurAuthorities by the trust itself under tech supervision of SwanandPatodkar, Consulting Engineer, Vaibhav Complex, Apna bazar Jalna Road, Aurangabad. The Building Inspected By Sub-Divisional Engineer.p.w.Sub-Div.(South)Aurangabad.Report As per Ref Ltr No.2 The Building seems to be of Good quality and all safety measures are taken and infrastructure is developed.

But Design (R.C.C) is not Approved by This Office and Quality Control tests are not carried by this office. So this office cannot certify the life of building, As well as structural stability of building. As per visual inspection, the building seems to be in Good Condition and good for use as a school building.

Copy to :- Sub-Divisional EngineerPW(South)subDivision
A'bad.For information

Executive Engineer
Public Works Division.
Aurangabad.